

- Unique on a torque wrench, the TimeStrip[®] gives a visual indication that the wrench is due for re-calibration.
- Supplied in a molded plastic carrying case for protection.

14004 SUPPLIED WITH EXTENSION HANDLE TO REDUCE OPERATOR EFFORT.

PART NO.

150112K

150114K

150115K

14196

1-7-

Replacement Ratchet Kit

PRICE EA

\$67.25

\$62.50

\$75.50

\$94.50

PART NO.	DRIVE SIZE	TORQUE RANGE		LGTH	WT.	PRICE
		FT-LBS	Nm	(IN)	(LBS)	EACH
15002	3/8"	7.5-37.5	10-50	13.2	1.5	\$230.50
15003	1/2"	15-75	20-100	15.2	2.1	\$236.00
15004	1/2"	30-150	40-200	18.5	2.4	\$263.50
15006	1/2"	50-250	60-340	26.9	3.3	\$318.00
15007	3/4"	60-300	80-400	27.0	4.3	\$433.00
14004	3/4"	370-1100	500-1500	81.5	18.2	\$1,501.00

* 2 Piece Tool: Handle = 61.81" long, Extension = 19.69" long



318

LASTIC PROCESS 8303 CORPORATE PARK DRIVE MACEDONIA, OHIO 44056-2300 216-367-7000 • FAX: 216-367-7022 TOLL FREE: 800-321-0562 EQUIPMENT, INC.

PART NO.

150106K

150105K

N/A

N/A

Spare Mushroom Head Sq. Drive

PRICE EA

\$69.90

\$71.30

N/A

N/A

NIST Certified Factory Recalibration available.

6385 MONTESSOURI STREET LAS VEGAS, NEVADA 89113-1186 702-433-6385 • FAX: 702-433-6388 TOLL FREE: 800-258-8877 e-mail: sales@ppe.com Toll Free: USA, Canada & Mexico 800-362-0706

Order Fax: 800-223-8305