



# WARNING SAFETY SIGNS



Warning signs must have a black pictogram on a yellow triangle with a black border.  
Hazard signs must be displayed to warn people to be careful or take precautions where hazards exist.  
The General Warning Sign can only be used in combination with other warning signs.

Form Compliments of PPE

## KNOW YOUR SAFETY SIGNS!



**W001**  
General warning sign



**W002**  
Warning; explosive material



**W003**  
Warning; Radioactive material or ionizing radiation



**W004**  
Warning; laser beam



**W005**  
Warning; Non-ionizing radiation



**W006**  
Warning; Magnetic field



**W007**  
Warning; Floor level obstacle



**W008**  
Warning; Drop (fall)



**W009**  
Warning; Biological hazard



**W010**  
Warning; Low temperature/  
freezing conditions



**W011**  
Warning; slippery surface



**W012**  
Warning; Electricity



**W013**  
Warning; Guard dog



**W014**  
Warning; Fork lift trucks and other  
industrial vehicles



**W015**  
Warning; Overhead load



**W016**  
Warning; Toxic material



**W017**  
Warning; Hot surface



**W018**  
Warning; Automatic start-up



**W019**  
Warning; Crushing



**W020**  
Warning; Overhead obstacles



**W021**  
Warning; Flammable materials



**W022**  
Warning; Sharp elements



**W023**  
Warning; Corrosive substance



**W024**  
Warning; Crushing of hands



**W025**  
Warning; counter rotating rollers



**W026**  
Warning; Battery charging



**W027**  
Warning; Optical radiation



**W028**  
Warning; Oxidizing substance



**W029**  
Warning; Pressurized cylinder



**W030**  
Warning; Hand crushing  
between press brake tool



**W031**  
Warning; Hand crushing  
between press



**W032**  
Warning; Rapid movement of  
workpiece in press brake



**W033**  
Warning; Barbed wire



**W034**  
Warning; Bull



**W035**  
Warning; Falling objects



**W036**  
Warning; Fragile roof



**W037**  
Warning; Run over by remote  
operator controlled machine



**W038**  
Warning; Sudden loud noise



**W039**  
Warning; Falling Ice



**W040**  
Warning; Roof avalanche

© Copyright 2016 Plastic Process Equipment, Inc. Note: PPE customers may reproduce this form only in it's entirety.



**PLASTIC PROCESS EQUIPMENT, INC.**

www.ppe.com • e-mail: sales@ppe.com

**PPE WEST** 6385 Montessouri Street, Las Vegas, Nevada 89113  
702-433-6385 • 800-258-8877 • Fax: 702-433-6388

**PPE SOUTH** 11218 Challenger Avenue, Odessa, Florida 33556  
727-834-8888 • 800-282-6783 • Fax: 727-834-8873

8303 CORPORATE PARK DRIVE, MACEDONIA (Cleveland), OHIO 44056, USA

Toll Free: USA, Canada & Mexico  
**800-362-0706**

216-367-7000 • Toll Free: 800-321-0562 • Fax: 216-367-7022 • Order Fax: 800-223-8305