

BRASS SPRUE PULLERS

WITH REPLACEABLE BRASS SCREWS

1/2" Dia.

Brass screw

held in handle with set screw.






SOLID BRASS **WON'T DAMAGE** YOUR DIE OR **NOZZLES!**


> 1 Brass screw included.

5/8" Dia.









Brass screws can be ground narrow for penetration into thin wall parts. Drive in place and remove with brass pliers. Threads act like fish hooks. Some heating may be necessary.



BRASS RIBOUTS

TO REMOVE STUCK MOLDED PARTS



- FEATURES -

- Saves time on the production floor.
- · Extract stuck parts quickly and precisely.
- Reduce press down time.
- Protects your costly molds.
- Narrow profiles .024" & .032" to fit the thinnest ribs.





- INSTRUCTIONS -

- 1. Hold the Brass Ribout with brass pliers.
- 2. Heat Ribout with a torch.
- 3. Press the hot Ribout into your stuck plastic part.
- 4. Next pull the stuck plastic part out quickly.
- 5. Part is extracted.









PART NO.	DIMENSIONS Length x Width x Thickness	QTY PER PACK	PRICE PER PACK	
			1-4 PACKS	5+ PACKS
BR025	2" x 3/16" x .024"	10	\$16.70	\$15.40
BR030	2" x 3/8" x .032"	10	\$16.70	\$15.40



ASTIC PROCESS EQUIPMENT, INC.

8303 CORPORATE PARK DRIVE **MACEDONIA, OHIO 44056-2300** 216-367-7000 • FAX: 216-367-7022

TOLL FREE: 800-321-0562

6385 MONTESSOURI STREET LAS VEGAS, NEVADA 89113-1186 702-433-6385 • FAX: 702-433-6388 TOLL FREE: 800-258-8877

www.ppe.com

e-mail: sales@ppe.com

Toll Free: USA, Canada & Mexico 800-362-0706

Order Fax: 800-223-8305