







WIRING CONFIGURATIONS AND DIAGRAMS

These wiring configurations are provided to assist in the wiring of heating elements in parallel, series and 3-phase (Delta or Wye)



WIRING CONFIGURATION	HEATER ELEMENT VALUES (formulas and symbols)			
	VOLTS (e)	AMPS (i)	WATTS (W)	RESISTANCE (R)
Parallel	line volts (E)	$\frac{\text{line volts (E)}}{\text{element Ohms (Rn)}}$	$E \times i$	E/i
Series	$\frac{\text{line volts (E)}}{\text{\# of elements}}$	line amps (I)	$e \times i$	e/i
Delta	line volts (E)	$\frac{\text{line amps (I)}}{1.73}$	$e \times i$	E/i and $E/1.73 I$
Star (Wye)	$E/1.73$	line amps (I)	$e \times i$ and $E \times I/1.73$	$e \times i$ and $E/1.73 I$

